

Safety Issue Type: Recalls

July 31 2023 NHTSA Campaign Number: 23V534000

Engine Compartment Fire

A fire increases the risk of injury.

NHTSA Campaign Number 23V534000

Manufacturer Kia America, Inc.

Components POWER TRAIN

Potential Number of Units Affected 121411

Summary

Kia America, Inc. (Kia) is recalling certain 2017-2022 Niro and 2018-2022 Niro Plug-in Hybrid vehicles. Fluid may leak into the printed circuit board inside the hydraulic clutch actuator, which can result in an engine compartment fire.

Remedy

Dealers will inspect and replace the hydraulic clutch actuator as necessary and install a new fuse, free of charge. Owner notification letters are expected to be mailed September 29, 2023. Owners may contact Kia customer service at 1-800-333-4542. Kia's number for this recall is SC276.

Notes

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Affected Products (11)

Vehicle

MAKE	MODEL	YEAR
KIA	NIRO	2017-2022
KIA	NIRO PHEV	2018-2022

Associated Documents (3)

Chronology Report

RMISC-23V534-5049.pdf 86.768KB

<https://static.nhtsa.gov/odi/rcl/2023/RMISC-23V534-5049.pdf>

Defect Notice 573 Report

RCLRPT-23V534-5538.PDF 214.643KB

<https://static.nhtsa.gov/odi/rcl/2023/RCLRPT-23V534-5538.PDF>

Recall Acknowledgement

RCAK-23V534-6507.pdf 645.32KB

<https://static.nhtsa.gov/odi/rcl/2023/RCAK-23V534-6507.pdf>